

<b>ВЕС ПРЕФОРМЫ</b>	<b>ТИП ГОРЛА</b>	<b>КОЛ-ВО В КОРОБЕ</b>
13	PCO 1881	21 500
14,3	PCO 1881	21 500
14,50	PCO 1881	20500
15,5	PCO 1881	16 900
17	PCO 1881	12 240
17,5	PCO 1881	14 000
18	PCO 1881	16 900
18,5	PCO 1881	13 000
19,8	PCO 1881	14 000
19,9	PCO 1881	13 900
20,00	PCO 1881	14 400
20,50	PCO 1881	14 000
20,7	PCO 1881	14 800
22,6	PCO 1881	12 288
22,7	PCO 1881	12 900
22,8	PCO 1881	13 000
23	PCO 1881	10 080
25	PCO 1881	11 500
27	PCO 1881	8 568
28	PCO 1881	8 568
28,95	PCO 1881	8 016
29	PCO 1881	10 100
29,7	PCO 1881	8 500
30	PCO 1881	8 568
30,2	PCO 1881	9 450
30,5	PCO 1881	9 200
30,80	PCO 1881	8 016
31	PCO 1881	9 500
32	PCO 1881	9 200
33	PCO 1881	8 500
33,05	PCO 1881	8 016
33,7	PCO 1881	6 768
34	PCO 1881	7 500
34,2	PCO 1881	8 500
34,36	PCO 1881	8 016

<b>35,65</b>	<b>PCO 1881</b>	<b>8 016</b>
<b>36,7</b>	<b>PCO 1881</b>	<b>7 776</b>
<b>36,7</b>	<b>PCO 1881</b>	<b>7 500</b>
<b>37</b>	<b>PCO 1881</b>	<b>8 500</b>
<b>37</b>	<b>PCO 1881</b>	<b>8 500</b>
<b>38,75</b>	<b>PCO 1881</b>	<b>8 300</b>
<b>41</b>	<b>PCO 1881</b>	<b>7 700</b>
<b>42</b>	<b>PCO 1881</b>	<b>7 700</b>
<b>43,5</b>	<b>PCO 1881</b>	<b>7 700</b>
<b>45,9</b>	<b>PCO 1881</b>	<b>4 608</b>
<b>46,7</b>	<b>PCO 1881</b>	<b>6 480</b>
<b>50,7</b>	<b>PCO 1881</b>	<b>6 480</b>